3
U.S. Department
of Transportation
National Highway

Traffic Safety

Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393 DC METRO AREA (202) 366-0123 INTERNET: http://www.nhtsa.dot.gov

-11 111									
FOR AGENCY USE ONLY 258									
Date Received 31-JAN-2002	Od_or rt_dt od_rt up_lfr								
	Reference No.								
	757500								

							757588				
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer. Signature of Owner											
				VEHICLE I	NFORMATION						
Vehicle Ident, No. (V	/ehidle Ident. No. (VIN.) (Lineater at british of			Vehicle Make	Vehicle Model		Vehicle Year	Current	Ocometer Readin		
YV1VS29571F718163		divaria a na	VOLVO	540	S40						
Purchase Dat 01-JUL-2001 X New Duser				Zin Code	Engine Size Turbo Diesel (CID/CO/L Gas No Oylinders Fuel Injectio						
		City			<u> </u>		L		D : 4: Cb.in		
Transmission Type/ ☐ Manual ☐ Automatic	Antiloc X	K Brakes Yes No	3-Point Drivers	•		X Front Rear	Car Sport Ult 2-Door				
			F	AILED COMPONEN	T(S)/PART(S) I						
05100000	Part Name(s ENGINE STRUCTURE:BODY						ion Fi Left Right Front Rear		t(s iginal eplacement		
No of Failure	Date;	s) of Fallu	ire(s)				Failed Parks	NHTSA Previou	1		
	Milleage at Failure(s Part(s) Previously Vehicle Speed at Failure(s) Previously Yes No							'			
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), Hailure(s), Crash(es), and injury(ies) on the back of this form)											
Crash		Fire Number of Persons Injured (Number of Fatalitie			e E	Estimated Property Damag Reported to Polic					
□ тез □ но		Yes 🗌	No				☐ Yes ☐ No				
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)											

ABOUT 2 OR 3 WEEKS AGO I NOTICED SOMETHING THAT WAS HANGING FROM THE FRONT PART OF THE CAR. I CONTACTED THE DEALER AND THEY INFORMED ME IT WAS AN ENGINE COVERED, SINCE I AM LEASING THE CAR I REQUESTED TO BE REPAIRED. THE DEALER INFORMED ME IT WAS NOT COVERED BECAUSE THE DAMAGE WAS CAUSED BY ME. HE ALSO TOLD ME VOVOS ARE TOO LOW IN THE FRONT AND IF YOU PUSHED AGAINST A CAR BUMPER OR SOMETHING LIKE THAT IT WILL CAUSE THE ENGINE COVER TO FALL. AS FAR AS KNOW THIS IS NOT IN THE MANUAL AND WAS NEVER INFORMED OF THIS VOVOS PROBLEMS. THEY CHARGED ME \$151.06 TO REPLACE THE ENGINE COVERED. *AK

COMPLEONES & ENERGE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. You response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.